
# 5405-259

## **ASSEMBLY INSTRUCTION**


Pg: 1/2 Ver: 01



PACKING LIST			
No.!	Name of Item	Q'ty	U/M
1	Тор	01	pc
2	Legs	04	pcs
3	Center legs	02	pcs
4	Leave Top	01	pc
HARDWARE			
1	Hexa bolt & washer	08	pcs
2	Allen bolt & washer	06	pcs
3	Steel allen wrench	01	pc
4	Steel open wrench	01	pc

### INSTRUCTIONS:

- 1. Prepare 1 sheet of carton or any soft material on the floor.
- 2. Turn the top (P1) upside down and put it on a soft face (it is may be carton free from debris) that may cause damage to the item.
- 3. Insert the legs (P2) to the top (P1) then insert hexa bolt & washer, use steel open wrench to turn clockwise direction securely. Refer detail 'A'
- 4. Insert the center legs (P3) to the top (P1) then insert allen bolt & washer, use steel allen wrench to turn clockwise direction securely. Refer detail 'B'
- 5. Turn up the table. Item is ready to use. (adjustable glider for the table levelling if necessary refer detail 'C')




# 5405-259


## **ASSEMBLY INSTRUCTION**

Pg: 2/2 Ver: 01

#### WHEN OPEN LEAF


- -Open the lock of top panel (P1) see detail 'D', then open the top panel arrow guide. Refer sketch2.
- -Put the leaf panel (P4) to the top panel as per sketch 3, then close the top panel arrow guide and close the lock. Refer detail 'E'






#### WHEN CLOSE LEAF

- -Open the lock of top panel (P1) and the leave (P4) see detail 'F', then open the top panel arrow guide. Refer sketch 4.
- -Remove the leave panel (P4) out the top panel as per sketch 5, then close the top panel arrow guide and close the lock. Refer detail 'H'





Draw: H. Giang

Date: Nov. 19, 15